

Rough -
Mechanical failed.

① 8/23/21

② 9/7/21

③ 10/6/21

④ 10/20/21

Passed 10/21/21 Rough

Plumbing Rough

Failed

① 8/23/21

② 9/7/21

③ 10/6/21 ④ 10/20/21 failed

10/21/21 Passed

Electrical

8/16/21 Rough failed . MD Mike Refrino

8/20/21 Rough Passed MD

Buildings

3/12/21 Partial footing	Passed	JS Jim Stile
3/16/21 Rebar	Failed	JS
3/17/21 Rebar	Passed	JS
4/14/21 Foundation	Failed	TT Tom Tracey
4/20/21 Foundation	Passed	TT
10/26/21 Frame	Failed	TT

TOWNSHIP OF WEST ORANGE
BUILDING DEPARTMENT
66 MAIN STREET
WEST ORANGE, NJ 07052

DATE:

10/20/21

PERMIT:

2021 0283

BLOCK:

LOT:

For Information Call: (973) 325-4112

INSPECTION:

Pugh

INSPECTOR:

TJB

PERSON ON SITE:

Mr Vah

Base

Flat dry vent for Shower

✓

Stabilize ground work with sand

✓

1st

Recent Toilet

✓

Floor

Fittings not connected correctly

✓

Flat dry vent

ND

Pex on Spout

ND

2nd

Fl

WATER

Gas line in ceiling vent - need support

✓

Hall

Bath

Glue Toilets above in ceiling

ND

Pex on Spout

NP

Master

Pex on Spout

ND

Bushing on Gas line near meter

Note No vent for lav in Basement Future on AAD

For Information Call: (973) 325-4112

PERMIT: 2021-0263

BLOCK:

LOT:

INSPECTION:

INSPECTOR:

PERSON ON SITE:

Page	(1)	As per code No inspections - missing vapor barrier
	(2)	No sheeting inspection
	(3)	Interior plans passed no inspection - need revised plans see 4/14/21 notes
	(4)	Need revised plan for basement floor framing and over garage
	(5)	Question on unbracketed ductwork in garage area
	(6)	Garage layout not as per plans
18	(7)	Question on load bearing and frame in basement same direction - point load.
	(8)	Question on 2x12 @ 16 OC spanning 20'
	(9)	Revised Rear addition larger than approved plans
24	(10)	Question on Flash ceiling beam in master - 2x6 span
	(11)	Addition bigger than approved plan 1st and 2nd floor
	(12)	* Need complete new plans and Zoning approval
	(13)	Roof Framing not as per plans
	(14)	HVAC in unconditioned space to be R-8
		Rob. at 679-8483
	(15)	Both Sides to exterior
	(16)	Fireblock top of HVAC in walls
		Will need complete exterior inspection
		Need about survey - spoke with Arch.

TOWNSHIP OF WEST ORANGE
 BUILDING DEPARTMENT
 66 MAIN STREET
 WEST ORANGE, NJ 07052

DATE:

8/23/21

PERMIT:

2021 0283

BLOCK:

LOT:

INSPECTION:

Rough

INSPECTOR:

TJB

PERSON ON SITE:

Buley

For Information Call: (973) 325-4112

Base

Tub draining into vent for Basement Shower
 Support + pitch on 2" line basement ceiling (vent base Bath)
 Support on 1/2" line for
 2" waste line no pitch at all
 under Sizing

Water pipe support

1st

No lead on PVC - to Roof.

Vent 90° on laundry line

Wrong nail plates

Kitchen vent need to be 6" above flood line before horizontal
 insulate water line in outside walls

1st floor bath: Spout can not be fix

Need gauge on water 1.5" above the working pressure

1st fl. Bath wrong nail plates

Bath tub not installed correctly

insulation on PVC work in garage

Gar

Bath

ADJAC

1st fl

1st fl

Bath tub vent before trap

3" Sillage in ceiling not connected properly

No vent on 1st floor toilet

No pitch on 2" PVC line in ceiling

Per to Spout

1 1/2" vent in attic not connected properly

Nail plates

Floor flange too low

No trap in laundry bowl

Trap

Bath 2nd fl. Flange too low

Per on Spout

TOWNSHIP OF WEST ORANGE
BUILDING DEPARTMENT
66 MAIN STREET
WEST ORANGE, NJ 07052

For Information Call: (973) 325-4112

DATE:

8/23/21

PERMIT:

2021 0283

BLOCK:

LOT:

INSPECTION:

Rough

INSPECTOR:

TJB

PERSON ON SITE:

Bule/Buley

Laundry

Gas Sizing?
Nail plates.

R-Valve on Ductwork in Attic
Where is Attic access?

Backwater Valve in Basement
4" Cleanout within 5 Ft of Foundation (Wall)
in front

Water pipe undersized
Gas pipe undersized

Licensed plumber with Seal +
Identification at all inspections